


## ASSEMBLY INSTRUCTION NC\*FXX & NC\*MXX | XLR Cable Connector



- A Slide the boot onto the cable.
- B Prepare cable as shown.
- © Insert wires into the terminals and solder them.
- D Put chuck onto the cable.
  Attention: Pay attention to the guiding key.
- © Slide insert and chuck together into the housing.
- F Finish the installation by turning the bushing onto the connector.

