

Using The HDMI Continuity Tester

1. Make sure the HDMI Tester has (1) 9V battery installed in unit number 1 below.
2. Plug one end of your HDMI cable into unit labeled 1 below.
3. Plug other end of the HDMI cable into unit marked 2 below
4. Unit 2 has a series of 19 LEDs. If all the LEDs light up, the cable has full continuity. If none of the LEDs light up or only some then the cable does not have full continuity over all wires.

This tester measures the continuity of all 19 HDMI wires including Ethernet and Return Audio.

